


21 Excess-current

Overview technical documents/Home & Garden/High pressure cleaner cold water/Electric motor/K 5/K 502 MS

*FR (1.069-910.0)/Spare parts list K 502 MS/20 Pump set/21 Excess-current



21 Excess-current

Overview technical documents/Home & Garden/High pressure cleaner cold water/Electric motor/K 5/K 502 MS *FR (1.069-910.0)/Spare parts list K 502 MS/20 Pump set/21 Excess-current

Rez.daļas/nodil.pakļ.dajas	Poz.	Materiāla Nr.	Nosaukums	Daudzums	Pārdoš. vienība	no sēr. Nr.	līdz sēr. Nr.	Daž. informācija
	1	7.303-048.0	Screw M6x20 -St-R3R (In6Rd)	2.000	ST	0000000000	0000000000	
	2	5.064-127.0	Cover	1.000	ST	0000000000	0000000000	
	3	4.030-123.0	Moulded part complete only for replaceme	1.000	ST	0000000000	0000000000	VERSION 2
X-X	4	6.362-169.0	Gredzenblīve 12,0 X 2,0	1.000	ST	0000000000	0000000000	
X	5	4.580-675.0	Excess current complete	1.000	ST	0000000000	0000000000	
X	6	6.362-852.0	Gredzenblīve, pilns komplekts 3,69	1.000	ST	0000000000	0000000000	
	7	4.030-069.0	Moulded part complete only for replaceme	1.000	ST	0000000000	0000000000	VERSION 1
	11	5.060-642.0	Virzuļa vadotne	1.000	ST	0000000000	0000000000	
	100	2.883-826.0	PUMP SET	1.000	ST			