


50



| POS | Article no. | Description | Quantity | Unit |
|------|-------------|---|----------|------|
| 10 | 4.037-022.0 | Waste water tank complete | 1.000 | ST |
| 20 | | Chassis complete BD 38/12 | 1.000 | ST |
| 30 | | Steering pillar complete BD 38/12 | 1.000 | ST |
| 40 | | Brush-head | 1.000 | ST |
| 50 | 4.822-936.0 | Cable harness floor cleaner BD38_12 C | 1.000 | ST |
| 900 | 6.680-124.0 | Hose fresh water complete | 1.000 | ST |
| 901 | 6.371-250.0 | Diamond pad white set 5x Ø356 | 1.000 | ST |
| 901 | 6.905-060.0 | Slip microfiber Set 5x D356 | 1.000 | ST |
| 901 | 6.371-251.0 | Diamond pad yellow set 5x Ø356 | 1.000 | ST |
| 901 | 6.371-235.0 | Diamond pad green set 5x Ø356 | 1.000 | ST |
| 901 | 6.369-003.0 | Pad red | 1.000 | ZSA |
| 901 | 6.369-001.0 | Pad black set 5x | 1.000 | ZSA |
| 901 | 6.369-002.0 | Pad green | 1.000 | ZSA |
| 902 | 6.907-150.0 | Disk pad 355 | 1.000 | ST |
| 903 | 6.907-154.0 | Disc brush white | 1.000 | ST |
| 903 | 6.907-153.0 | Disc brush nature | 1.000 | ST |
| 903 | 6.907-151.0 | Disc brush red | 1.000 | ST |
| 903 | 6.907-152.0 | Disc brush black | 1.000 | ST |
| 904 | 5.122-016.0 | Centerlock reworking | 1.000 | ST |
| 9005 | 6.652-000.0 | Tank Ruhebehaltnis für die Li-Ionen-Bat | 1.000 | ST |