

Spare parts list



swingo

150 B



 **Diversey**TM
A SOLENIS COMPANY

Table of contents

TASKI swingo 150 B_1	3
Handle	4
Vacuum unit	6
Tank, Pump	9
Brush drive	11
Electrical diagram	14

TASKI swingo 150 B_1

Description


Handle

Vacuum unit

Tank, Pump

Brush drive


Electrical diagram



Handle

Article no.	Description	Quantity	Unit
4114420	Screw for plastic KA40x35	6	PC
4132851	Pressure switch	1	PC
4128400	Pressure switch	1	PC
4128401	Rocking switch	1	PC
4128512	Cover	1	PC
4029830	Raised cheese hd.screw M6x12	4	PC
xxxx	Lief. Nr.: 089050009 / 4x45	1	PC
4007480	Washer 4,3/12x1	3	PC
4128402	Latch	1	PC
4114420	Screw for plastic KA40x35	1	PC
4128403	Holder	1	PC
4128502	Handle	1	PC
4128404	Cover	1	PC
4132850	Electronics	1	PC
4132845	Cover compl	1	PC
4046950	Pan head tapp screw C 3,9x13	1	PC
4132852	Support set	1	PC
4132853	Cover	1	PC
7524166	TASKI Li-Ion battery 36V 6Ah	1	PC

Vacuum unit



swingo 150 B /1.1


02

Vacuum unit

Article no.	Description	Quantity	Unit
4128406	Handle	1	PC
4126537	Screw for plastic KA35x25	2	PC
4128407	Housing	1	PC
4080720	Pan head tapp screw C 3,9x16	4	PC
4080570	Clamp	2	PC
4008910	O-ring 5,28x1,78	1	PC
4128409	Filter	1	PC
4128410	Housing	1	PC
4128411	Gasket	1	PC
4015590	Screw for plastic KA35x10	9	PC
4128413	Cover	1	PC
4128416	Filter set	1	PC
4128415	Holder	1	PC
4083570	Screw for plastic KA40x18	3	PC
4128417	Valve set	1	PC
4007480	Washer 4,3/12x1	2	PC
4078180	Screw for plastic KA40x10	2	PC
4129702	Connection bloc 5-ways spez	1	PC
4114420	Screw for plastic KA40x35	1	PC
4128419	Cover	1	PC
4079480	Screw for plastic KA35x20	4	PC
4128420	Support	1	PC
4128422	Microswitch	1	PC
4062420	Screw delta PT Torx 30x16	1	PC
4128421	Support	1	PC
4128423	Gasket	1	PC
4126537	Screw for plastic KA35x25	5	PC
4128424	Gasket set	1	PC
4128425	Filter	1	PC
4132846	Vacuum motor 36V	1	PC
4128427	Filter	1	PC
4128412	Pipe compl	1	PC
4128497	Filter	1	PC
4128496	Cover	1	PC

Vacuum unit

Article no.	Description	Quantity	Unit
4055370	Hose 4/7 silikon	0,04	M
4128827	Housing	1	PC
4129938	Hose spec	1	PC
4131269	Quick nut M6 set	1	PC
4132847	Magnetic valve 36V	1	PC
4046850	Hose 3/6 silikon	0,34	M




swingo 150 B /1

03

Tank, Pump

Article no.	Description	Quantity	Unit
4128696	Cover	1	PC
4128433	Filter housing compl	1	PC
4128492	Filter	1	PC
4128493	Gasket	1	PC
4128494	Sealing ring	1	PC
4128495	Dosing cup	1	PC
4128434	Tank	1	PC
4128435	Valve set	1	PC
4128704	Hinge	1	PC
4129313	Support	1	PC
4131180	Shackle	1	PC




Brush drive

Article no.	Description	Quantity	Unit
4128438	Turning knob spec	1	PC
4128440	Brush housing	1	PC
4128441	Cover	1	PC
4128449	Roll set	2	PC
4128444	Holder set	1	PC
4122641	Screw delta PT Torx 40x16	2	PC
4128445	Hose set	1	PC
4128466	Cover	1	PC
4121420	Filter	1	PC
4083570	Screw for plastic KA40x18	3	PC
4132848	Motor 36V 150W xxA	1	PC
4025950	Screw for plastic KA40x16	2	PC
4128666	Belt stretcher compl	1	PC
4128452	Support set	1	PC
4132849	Electronics	1	PC
4072200	Pan head tapp screw B 3,5x13	4	PC
4128455	Wheel 40/17	2	PC
4128456	Bracket	1	PC
4007480	Washer 4,3/12x1	1	PC
4122655	Screw delta PT Torx 50x16	3	PC
4128457	Holder	4	PC
4128465	Pedal set	1	PC
4015590	Screw for plastic KA35x10	1	PC
4128458	Roll set	1	PC
4128459	Brush housing	1	PC
4128460	Wheel compl	2	PC
4128513	Holder	1	PC
4128461	Bearing compl	1	PC
4015590	Screw for plastic KA35x10	8	PC
4128462	Cover	1	PC
4128463	Protecting profile	1	PC
4128464	Lever	1	PC
4128448	Toothed belt 8-327	1	PC
4128972	O-ring 39,5x2,6	1	PC

Brush drive

Article no.	Description	Quantity	Unit
4128828	Toothed belt 8-174	1	PC
4129053	Cover	1	PC
4099330	Turning knob 16	4	PC
4129258	Holder compl	2	PC
4129046	Blade 23/2,5x350	2	PC
4128917	Squeegee body	2	PC
4052550	Hexagon screw M5x14	4	PC
4129043	Blade 21/2x350	2	PC
4129047	Squeegee compl	2	PC
4129596	Latch	1	PC
7517663	TASKI swingo 150 Exchange Squeegee Kit	1	PC
7516236	Cylindrical brush standard Swingo 150	1	PC
7516237	Cylindrical brush hard for Swingo 150	1	PC
7519049	Activefibre Padroll for swingo 150	1	PC

Electrical diagram



SWINGO 150
36V DC Li - Ion battery

WIRING DIAGRAM

- 1 - Battery
- 2 - Main switch
- 3 - Vacuum switch
- 4 - Electro valve switch DC
- 5 - Wires kit electric panel
- 6 - Wires kit upper housing
- 7 - Electro valve
- 10 - Terminal block
- 11 - By-pass vacuum motor 36V DC
- 12 - Microswitch
- 13 - Wires kit base
- 14 - Circuit board Vacuum motor
- 15 - Brush motor 36V DC
- 16 - Wire kit vac / base
- 17 - Circuit board Brush motor

