


40 Switch box

Professional \ Floor cleaner \ Walk behind \ BD 530 BAT *EU \ Spare parts list BD 530 BAT \ Switch box



40 Switch box

Professional \ Floor cleaner \ Walk behind \ BD 530 BAT *EU \ Spare parts list BD 530 BAT \ Switch box

KÄRCHER

POS	Article no.	Description	Quantity	Unit
14	2.883-854.0	Spare part set	1	PC
29	5.044-095.0	Holder storage cabinet	1	PC
6	6.303-262.0	Oval head screw 2,9X 16	4	PC
31	6.373-670.0	Pipe clamp	1	PC
1	6.601-301.0	Chest and mounting plate LAENGE 630 MM	1	PC
32	6.633-235.0	Relay 24 V	1	PC
2	6.633-389.0	Relay 24VDC / 100A	1	PC
22	6.641-355.0	Cable gland PG9	1	PC
20	6.641-357.0	Cable gland PG11	1	PC
23	6.641-366.0	Locknut PG 9	1	PC
21	6.641-367.0	Locknut PG11	1	PC
18	6.641-368.0	Locknut PG21-PA DIN 46320	1	PC
9	6.643-686.0	Strip terminal six-pole	1	PC
7	6.643-687.0	Strip terminal four-pole	1	PC
13	6.644-275.0	Fuse holder	1	PC
10	6.644-276.0	Plate	1	PC
17	6.644-302.0	Fuse holder	2	PC
30	7.303-104.0	Screw 5x16 -A2-70 (IN6RD)	1	PC
3	7.306-077.0	Screw M5x16 -8.8-R2R (In6Rd)	3	PC
5	7.306-118.0	Screw M 6x35 -8.8-R3R (In6Rd)	2	PC
28	7.306-119.0	Cylinder head screw M8x12 -A2-70 ISO 47	3	PC
11	7.311-001.0	Hexagon nut M4 -6-A2E ISO 4032	6	PC
8	7.311-002.0	Hexagon nut M5 -6-A2E ISO 4032	3	PC
4	7.311-003.0	Hexagon nut M6 -8-A2E ISO 4032	6	PC
24	7.312-003.0	Washer 6 -200HV-A3E ISO 7089	4	PC
25	7.312-167.0	Toothed lock washer A6,4-FSt-A3E DIN 6797	2	PC
26	7.312-278.0	Washer 5-200HV-A2E ISO7093-1	1	PC
19	7.777-999.0	Stockpiling discontinued	1	PC