



22 Thrust guidance

| Rez.daļas/nodil.pakļ.daļas | Poz. | Materiāla Nr. | Nosaukums | Daudzums | Pārdoš. vienība | no sēr. Nr.. | līdz sēr. Nr. |
|----------------------------|------|---------------|--------------------------------------|----------|-----------------|--------------|---------------|
| X-X | 1 | 4.553-282.0 | Piston complete only for replacement | 3.000 | ST | 0000000000 | 0000000000 |
| X | 2 | 5.115-991.0 | Washer | 3.000 | ST | 0000000000 | 0000000000 |
| X | 3 | 5.332-167.0 | Spirālveida atspere | 3.000 | ST | 0000000000 | 0000000000 |
| X-X | 4 | 6.363-228.0 | Gredzenblīve 114 x 3 | 1.000 | ST | 0000000000 | 0000000000 |
| | 5 | 5.060-936.0 | Taisnvirziena vadotne D 20 | 1.000 | ST | 0000000000 | 0000000000 |
| | 6 | 7.306-094.0 | Skrūve M6x25 -8.8-R3R (In6Rd) | 2.000 | ST | 0000000000 | 0000000000 |
| X-X | 7 | 7.306-091.0 | Cil. galvas skr. M12x90- 8.8-A3E ISO | 4.000 | ST | 0000000000 | 0000000000 |
| X-X | 8 | 6.365-052.0 | Gredzens ar gropi 20X28X6/8 | 3.000 | ST | 0000000000 | 0000000000 |
| X-X | 9 | 5.115-537.0 | Paplāksne | 3.000 | ST | 0000000000 | 0000000000 |
| X-X | 10 | 6.365-380.0 | Zemspiediena blīvju komplekts | 3.000 | ST | 0000000000 | 0000000000 |
| X-X | 11 | 5.112-713.0 | Bush | 3.000 | ST | 0000000000 | 0000000000 |
| X-X | 12 | 6.362-092.0 | Gredzenblīve 36,0 X 2,0-NBR 70 | 3.000 | ST | 0000000000 | 0000000000 |
| X-X | 13 | 5.115-538.0 | Paplāksne | 3.000 | ST | 0000000000 | 0000000000 |
| X-X | 14 | 6.365-377.0 | Gredzens ar gropi 20x30x6 | 3.000 | ST | 0000000000 | 0000000000 |
| X-X | 15 | 6.365-378.0 | Balstgredzens 20x30x4,2 | 3.000 | ST | 0000000000 | 0000000000 |